

Fires in SAIC Dorms for the Period of 1/1/2007 - 1/1/2009

<u>Building Address</u>	<u>Fire Incidents in the last two years.</u>	<u>Time & Date</u>	<u>Property damage?</u>	<u>Cost of Fire Damage.</u>	<u>Injuries?</u>	<u>Deaths?</u>	<u>Nature</u>
162 N State	1 (room 1501)	5:30 PM 11/14/2007	Yes	\$70,000	0	0	Garbage can fire in bathroom caused by cigarette
7 W Madison	N/A	N/A	N/A	N/A	N/A	N/A	N/A



InReD

Incident Report Data

The Art Institute of Chicago - The School of the Art Institute of Chicago
 Department of Protection Services - Campus Security

INCIDENT NUMBER	IR-071114-180452	
INCIDENT TITLE	FIRE	
Date of Incident	11/14/2007	Time of Incident 17.30
Building	162 N. State (1500)	
Incident Created By	MCCRARY, GEORGE L.	
Responsible Supervisor	THOMAS, LEONARD	
Organization	AIC	
Incident Location	State Building	
Location Detail	15th Floor	
Category	Fire	
Sub Category	Actual	
Type	Structure Fire	
Damage to Property	No	Value 0
School Category	FIRE AND SAFETY - RESIDENCE	
Clery Category		
School Disposition	Cleared by Service	

Narrative On the above date and time, the Honeywell smoke detector panel sounded stating the following: Alarm active 15th floor Rm #1501 0001 Alarm Active 15th floor A001 S00 000 T000 M000. Immediately after the Cyberus Pyrotronics Fire panel sounded a fire alarm along with the Annunciator Fire panel stating the 15th floor room #1501 sprinkler system was activated. The horns sounded and the building began to be evacuated. I contacted Supervisor L. Thomas and Patrol officer Y. Barnes. Officer Y. Barnes did a sweep of the floor checking rooms #1010 (Resident Michael Nesmith #2261469) and #602 (Requested per Prostaff) for students in need of evacuation assistance. None of the resident were present in the rooms at the time.

are residents of room #1501. Fire engine # 13 and #6 arrived on the scene at 1750. Supervisor L. Thomas had arrived 15mins prior to C.F.D's arrival (1735hrs). Chicago Patrol Officer R. Burnett arrived at 1740hrs to assist with crowd control. I paged the engineer on duty Gregory Parks (#9993578) and he was enroute to the building at 1755hrs. At 1805hrs, Supervisor L. Thomas escorted C.F.D. to the pump room located in the basement mechanical room so C.F.D could attempt to shut off the sprinkler water supply. The sprinkler pumps were shut down and drained at 1825hrs. Immediately after, Supervisor L. Thomas, the C.F.D (Fire Cheif), and Officer Y. Barnes went to room #1501 to check for the cause of the sprinkler activation and damages. At 1840hrs, Supervisor L. Thomas came back to the desk and stated the the 15th floor was partially flooded. He also stated that the restroom in rm #1501 had fire damage. Deborah Martin (#576071) and Robert Schlingman (#560210) came to assist. At 1850hrs, C.F.D. along with engineer Gregory parks went to attempt to repair the sprinkler head in #1501 so the sprinkler pump could be reactivated. At 1935hrs the sprinkler pumps were back online and the Cyberus Pyrotronics fire panel and the Annunciator panel were reset by C.F.D. immediately after. Student were allowed to check back into to the building at approximately 2000hrs less access to floors #13, #14, and #15 due to water damage. All residents of the above mentioned floors were directed to the Media lounge located on the 16th floor (#1609). ABM housekeepers were dispatched to the before mentioned floors by Bert Schlingman to start the clean up process. Officers along with RA's were station on floors #13, #14, and #15 to keep the floors clear of building residents while the clean up was in process. At 2320hrs, students/residents who resided in following rooms were allowed to enter there rooms on the 13th, 14th, and 15th floors. (All of the 13th floor, All of the 14th floor, #1506 to the south end rooms) Officer R. Burnett was posted at the elevators on the 15th floor to keep